Notebook, N-02-04-18.2

XE-172 N-02-04-18.1

35
13
105
35
45 20
91 0

13
20
260

Aluminum ✓
Boron ✓
Silicon ✓
Cobalt ✓
Nickel ✓
Magnesium ✓
Antimony ✓
Bismuth ✓
Chromium ✓
Lead ✓
Iron ✓
Zinc ✓
Cadmium
Manganese
Copper ✓
Tin
Phosphorous
Sulphur
Molybdenum
Sodium
Tellurium
tungsten ✓

Selenium
Uranium
Thorium
Zirconium
Cerium
Titanium
Lithium
Arsenic
Silver ✓
Niobium
Vanadium
Didymium
Tantalum
Yttrium

April 15 1902

Alloys for Thermo-other experiments

Tungsten		Aluminium	
19		1	
18		2	
17		3	
16		4	
15		5	
14		6	
13		7	
12		8	
11		9	
10		10	—
9		11	—
8		12	—
7		13	—
6		14	—
5		15	—
4		16	— 1726
3		17	— 1866
2		18	1934
1		19	— 1938

Apr 30 tried W10 Al10 used crystals as a flux for Al. used a high heat. On opening could found only a black mass. With bright yellow crystals [illegible]

centered through it showed some of the crystals
Tried same alloy again ~~but not get a~~ with less heat. The alloy produced was not homogeneous so will ~~not~~ make ~~only~~ those with more Al than 5.0%

Tungsten	Boron
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

Tungsten	Silicon
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

May 6

Tungsten		Cobalt
19		1
18		2
17		3
16		4
15		5
14		6
13		7
12		8
11		9
10		10
9		11
8		12
7		13
6		14
5		15
4		16
3		17
2		18
1		19

Complete. May 6

Started Apr 28. Finished Apr 29 1800

Wallace 1M

Tungsten,	Nickel	
19	1	14.78
18	2	15.5
17	3	17.98
16	4	16.81
15	5	17.69
14	6	18.45
13	7	18.74
12	8	18.71
11	9	18.70
10	10	18.13
9	11	18.85
8	12	18.69
7	13	18.98
6	14	19.53
5	15	17.65
4	16	19.20
3	17	19.36
2	18	19.79
1	19	19.8

Made W14 Ni1 W10 Ni10 + W6 Ni14 first alloys marked a beginning of series

It was impossible to fuse the first two alloys of the series your would see the Ni melt & be absorbed by the W. By using about 95 amperes for

OVER

[9]

about five minutes the W would become a thick pasty mass but not a clear fusion although the lime of the cruc was softened so much that it was found to be crystalline on cooling.

Alloys containing 30 % + over of Ni melt much more easily + completely + make nice buttons

Tungsten	Magnesium
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

apr 29

Tungsten	Antimony
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10 —
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

Sb is all volatilized out.
Same as Bi

Started Apr 29 10.00 A.M.

Tungsten	Bismuth
19	1
18	2 —
17	3
16	4
15	5
14	6 —
13	7
12	8
11	9
10	10 —
9	11
8	12
7	13
6	14 —
5	15
4	16
3	17
2	18
1	19

It is impossible to completely fuse the W it only gets slightly pasty + sticks together nicely when the Bi is thrown. The heat is sufficient to completely volatilize Bi when less than ~~1 of~~ 10 g of Bi are used when more than this amount of Bi is used some remains

fact it does not appear to have combined with the W at all

May 13 *

Tungsten	Lead
19	1
18	2
17	3
16	4
15	5 ——
14	6 ——
13	7
12	8
11	9
10	10 ——
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

The Pb above will seem to alloy with the W. The W does not melt in the furnace it remains as a porous mass which simply wicks up the Pb noticed this in W 10 Pb 10 where the W sucked up 4 g. of Pb + the remainder of the Pb was

left in globules sticking to it
when I squeezed the button with
the pincers more lead came
out of it in globules

Tungsten	Zinc
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19


Tungsten 19 Cadmium.


Tungsten. 19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
Manganeeeee 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19

Apr 29 Finished Apr 30 11 P.M.

Tungsten	Copper	
19	1	15.7
18	2	
17	3	
16	4	17.61
15	5	18.58
14	6	18.3
13	7	17.
12	8	15.75
11	9	16.05
10	10	16.93
9	11	17.99
8	12	17.9
7	13	17.65
6	14	19.24
5	15	17.0
4	16	15.
3	17	18.63
2	18	19.68
1	19	

alloys with less than about 5% Cu do not seem to be homogeneous there appears to be an alloy in the center surrounded by an compound W. ~~Cu~~ probably due to incomplete fusion I am making alloy W10 Cu10

I noticed that the W melted + became very fluid at first, commenced to combine with the W + became thicker as it took up more W + could not be brought again into a fluid state even with prolonged heating with 90 amperes.

Jupiter,	Jim
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

May 13

Tungsten	Phosphorous
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19


Tungsten 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1
Sulphur 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

Tungsten		Molybdenum
19		1
18		2
17		3
16		4
15		5
14		6
13		7
12		8
11		9
10		10
9		11
8		12
7		13
6		14
5		15
4		16
3		17
2		18
1		19


Tungsten 19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
Chromium 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19


Tungsten 19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
Sodium 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19


Jungpaten
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
Tethuriuni
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19


Tungsten 19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
Selenium 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19


Tungsten 19 Uranium 1
18 2
17 3
16 4
15 5
14 6
13 7
12 8
11 9
10 10
9 11
8 12
7 13
6 14
5 15
4 16
3 17
2 18
1 19

Tungsten	Thorium
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19


Jungaten 19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2.
1
Zirconium 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19


Tungsten 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1
Cerium 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19


Tungsten 19 Titanium 1
18 2
17 3
16 4
15 5
14 6
13 7
12 8
11 9
10 10
9 11
8 12
7 13
6 14
5 15
4 16
3 17
2 18
1 19


Tungsten 19 Lithium 1
18 2
17 3
16 4
15 5
14 6
13 7
12 8
11 9
10 10
9 11
8 12
7 13
6 14
5 15
4 16
3 17
2 18
1 19


Tungsten 19 Arsenic 1
18 2
17 3
16 4
15 5
14 6
13 7
12 8
11 9
10 10
9 11
8 12
7 13
6 14
5 15
4 16
3 17
2 18
1 19


Jumpolen 19 Silver 1
18 2
17 3
16 4
15 5
14 6
13 7
12 8
11 9
10 10
9 11
8 12
7 13
6 14
5 15
4 16
3 17
2 18
1 19

Apr 30

Tungsten	Iron
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19

Started on W10 Fe10 Fe fused OK but W did not it seemed to form a pasty mass with Fe + the alloy required ~~[illegible]~~ considerable ~~[illegible]~~ heating before it appeared to be homogenious in the furnace. Next made W6 Fe14 This fused more easily

but made a more porous button perhaps because I didn't use powdered coke ~~& I~~ throwing the coke on the W10 Fe10 alloy caused quite a vigorous reaction which threw some of the alloy out of the furnace so did not use it in ~~[illegible]~~ W6 Fe14

Tungsten	Niobium
19	1
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19


Tungsten 19 Vanadium 1
18 2
17 3
16 4
15 5
14 6
13 7
12 8
11 9
10 10
9 11
8 12
7 13
6 14
5 15
4 16
3 17
2 18
1 19

Tungsten	Ordinyium
18	2
17	3
16	4
15	5
14	6
13	7
12	8
11	9
10	10
9	11
8	12
7	13
6	14
5	15
4	16
3	17
2	18
1	19


Tungsten 19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
Tantalum 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19


Jungsten 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1
Yttrium 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19